

**AMENDMENTS TO THE ABSTRACT**

Please substitute the following paragraph(s) for the abstract now appearing in the currently filed specification:

A rotary cutterhead, which is the main part of a cutting machine, is placed in a stationary frame and guides are mounted to the stationary frame to permit a transporter unit for feeding the material into a cutting zone of the cutterhead to be moved along the guides relative to the stationary frame. The guides are horizontal and preferably placed at a height so as to make safe and full access to the cutting zone possible.